

Pictures of the South Flats Island taken by DNR on 1/5/17



Pic #1: Southwest corner of the island –much shoreline vegetation



Pic #2: Southeast Corner of the Island – note trees along the berm



Pic #3: SE corner of the island looking to the W – much vegetation



Pic #4: SE corner of the island looking across the Island to the NW – much vegetation



Pic #5: SE corner of the island looking at sediment cracks – cracks show ~1 ft thick solid clay



Pic #6: SE corner of the island looking along the channel at the back of the Island



Pic #7: NW corner of the island looking across the Island to the E – much vegetation



Pic #8: NW corner of the island looking at the shoreline protection mats – much vegetation



Pic #9: NW corner of the island looking across the Island to the S – much vegetation



Pic #10: NW corner of the island looking along the shoreline protection mats – much vegetation